



Audi A3 (8L1) ***All models with sliding/tilting sunroof*** ***and the control unit on the central-*** ***locking pump***

Sunroof cannot be closed via the “comfort-closing” function.

If there are complaints with these vehicles that the sunroof cannot be closed via the “comfort-closing” function, one possible cause is the central-locking pump. If the sunroof is closed using the comfort-closing function and there is an interruption during the process, due to inadvertent releasing of the button or radio interference, the sunroof will not close further when the closing button is pressed again. The electric window winders, however, close further. In order to close the sunroof, the vehicle must be opened and closed again using the remote control. Only then will the comfort-closing work again in the case of the sunroof as well. In order to eliminate the fault, a new, modified central-locking pump with control unit must be fitted. The modified central-locking pumps, from production date 20.07.2000 (recognizable via the stamping 20072000 on the underside) have improved software.

Note:

The closing system is equipped with an anti-play function. Only 20 “comfort-opening/closing” signals are possible one after another, after that, the system is blocked and becomes active again only after switching the ignition on/off.